PVT (PRESSURE & VACUUM TESTER) - GAUGE PRESSURE OR VACUUM FOR CANS AND BOTTLES



The "PVT" are used to measure pressure or vacuum of cans or bottles

Simply place the sample under the entity manometer vacuum-meter and lower the lever.



Advantages:
- Easy to use
- Available in analog or digital
- Different accuracy class
- Fits all samples

Specifications:
Range: -1 bar to 10 bar
Resolution: on request
Precision : 0.1% to 5% according to model
Weight: 3 Kg